






20
















Fig. 2(b)








Fig. 5(a)
PRIOR ART



Fig. 5(b)
PRIOR ART



Fig. 6

PRIOR ART material roll-forming (a series of 15 to 20 rolls) 1 cutting flash butt welding correction in roundness finishing the welded part (5 to 6 steps) polishing the whole circumference making holes surface treatment